Packaging

Work Ordo May 10, 2010 9		521											Page 1
Revision ID:	D4017-7			Accept						Setup	Start Stop		
	10/05/2010	Start Qty: 3.00 Req'd Qty: 3.00				Cust Item I Customer:	D:				Stop	1 <b>110</b> 111161 <b>1</b>	
Approvals:	Process Pla	n:	Date: 10-5-10	Tooling: SPC (Y/N):			ite:			Run	Start Stop		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours		Draw Number	Draw Rev.	Plan Code	Accept	t Rej		Reject Number	Insp. Stamp
Draw Nbr		ision Nbr											
D4017	В												
Large Fab	••		be as per dwg D4017 r and remove identify marks	0.00 0.00 SA	ρ	10-05	-29		3				
QC Quality Control		QC5- Inspect part con	npleteness to step on W/O	0.00					3	PD	PO.09	5.19	
120		Identify as per dwg &	Stock Location: WA	0.00 S.	ΑD	10-05	- <u>-</u>	7	(3)	<b>)</b>			
Packaging		Memo		0.00			** , /			/		-	

W/O:			V	ORK ORDER CHANGI	ES			
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			· · · · · · · · · · · · · · · · · · ·					
			1				<u>.</u>	
			<del> </del>					
Part No	:	PAR #:	Fault Ca	tegory:	NCP: Voc. N	lo DOA:	Data	
		esolution:						
NCR:				DER NON-CONFORMA			Date	
DATE	CTED	Description of NC		Corrective Action Section	on B	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		:						;
		`						
	.1	<u> </u>	1					

### Work Order ID 58521

May 10, 2010 9:18:55 AM

**Required Date:** 13/05/2010



Page 2

Item ID:

D4017-7

Accept

Setup Start

Stop



**Revision ID:** 

Item Name: Rib

10/05/2010

QC:

Start Qty: 3.00

Req'd Qty: 3.00

QC21- Final Inspection - Work Order Release

**Cust Item ID: Customer:** 

Reference:

**Start Date:** 

Approvals:

Process Plan: Date:

Operation

Description

Date:

**Tooling:** SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Date:

Run

Start

Stop

Sequence ID/

Work Center ID

130

Memo

0.00

0.00

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Oty

Reject Insp. Number Stamp

Quality Control

W 1005.20

Dart Aerospace Ltd
--------------------

W/O:			WC	RK ORDER CHANC	GES				<del></del>
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•				,					
			#						
			<del></del>			·			
		·							
				. :			ŀ		
Part No	•	PAR #:	Fault Cate	, gory:	NCR: Yes	No <b>D</b> Q	A:	Date:	
		solution:							
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR	R)			
DATE	STEP	Description of NC			tion B	Verifi	cation	Approval	Approval
	0121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
				•*•					
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
				·					
· .									
									10.32

### **Picklist Print**

May 10, 2010 9:19:00 AM

Work Order ID: 58521

Parent Item: D4017-7

Rib

Parent Item Name:

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC IPP Rev:C as per dwg RevB

per dwg RevA DD 10.03.06 verified by:EC

DD 10.04.16 verified by:EC

IPP Rev:B as

Start Qty: 3.00

Required Date: 13/05/2010

Required Qty: 3.00

Component Item ID/

Replacement Mfg/ M304TS0.750W.049

Purchased

Bin Primary No

Last

Route 100

Unit of

Qty on

Qty per Kit Qty

**Start Date:** 10/05/2010

Date

Status

Page 1

304 SQ Tube .75x.75x.049W

343.9493

Loc Code

0.0675

Location Loc Oty MAT 200 113763 0 114323 200 MAT017 143.9493368 113763 . 24.25 114298

119.699337

. . . .

	•									
W/O:			WC	ORK ORDER CHANG	GES					
DATE	STEP	PR	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,							
				4						
Part No	:	PAR #:	Fault Cate	gory:	NCR:	Yes N	lo DQA	۱:	_ Date: _	
-	Re	solution:	Disposition	n:	QA: N	I/C Clo	sed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (	NCR)				
DATE	STEP	Description of NC	<u> </u>		ction B		Verific	ation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	,	Sign & Date	Section		Chief Eng	QC Inspector
								•		
										;
										-
									÷	

QTY -041 ITEM DESCRIPTION D4017-041 SHORT BASKET BASE ASSY (350) D4017-101 TUBULAR ASSY (350 SHORT BASKET) 10 14 14 13 D2581 2 MOUNTING BRACKET 3 2 D2931 BUMPER D3913-15 WIDE HANDLE PLATE 1 3 D4016-1 HINGE HALF, BASE D4020-3 MESH (350 BASKET SHORT BASE) D4020-11 END MESH, BASKET D4021-1 HANDLE PLATE D4021-5 2 BLANKING PLATE 10 AN3-10A BOLT 11 2 AN960JD8 WASHER 12 MS20600AD4W3 2 RIVET 13 MS21042L3 6 NUT 14 12 NAS1149F0332P WASHER 3(1)(12) A 3 11 12

D4017-041 SHORT BASKET BASE ASSY (350) (MESH SHOWN LOCALLY FOR CLARITY)

SHOPCORY

RETURN TO

ENGINEERING.

UNCONTROLLED COS

SUBJECT TO AND THE REAL OF

WITHOUT ATTACE

BS10-5-10

DESIG	N A	S DART AFROS	ACEL	īn
REV.	L	DESCRIPTION	BY	DATE
A	NEW ISSUE		AJS	10.03.04
В	NAS1149C0332 RENUMBERED	REPLACED WITH QTY 1 D3913-15; AN3-10, C10A; NAS1149F0332P WASHER WAS R; SECTION F-F UPDATED (08-2); ITEMS DETAIL D UPDATED (A4-3)	JPH	10.03.25

DRAWN	JBH VAS	HAWKESBURY, ONTARIO, CANADA
CHECKED		DRAWING NO. REV B
MFG, APPR.	M\	D4017 SHEET 1 OF 5
APPROVED	M	TITLE SCALE
DE APPR.	-#	SHORT BASKET BASE ASSY (350) NTS

10.03.25


DATE

D


С

NOTES:
1) MATERIAL: N/A
2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: NONE
7) WEIGHT: 28.8 ibs APPROX
8) INSTALL AFTER FINISH
9) MASK HOLES PRIOR TO POWDER COAT
10) WELD PER DART QSI 004


	•								
W/O:		·	W	ORK ORDER CHANG	ES	<del></del>			-
DATE	STEP	PR	OCEDURE CHA	INGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	agory:	NCR: Yes	No DO	Δ.	Date:	
		esolution:							
NCR:				ER NON-CONFORMA					
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval
	0,2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
		pho-							
									,
•									
							121.		
									ļ




	•								
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<b></b>									
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DO	)A:	Date: _	
	Res	solution:	Disposition	າ:	QA: N/C	Closed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	<del></del>		ion B	Verif	ication	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector
							****		
									  -



	•									
W/O:			WC	RK ORDER CHAN	GES					
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,							
Part No	•	PAR #:	Fault Cate	jory:	NCR:	Yes N	lo DQ	<b>A:</b>	Date:	I
		olution:								
NCR:		,	WORK ORDE	R NON-CONFORM	IANCE (	(NCR)				
DATE	STEP	Description of NC			ction B		Verific	ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	!	Sign & Date	Secti		Chief Eng	QC Inspector
			1							
							1			
			,							`
							į			
<del></del>										
										<u> </u>



	•								
W/O:			WO	RK ORDER CHANGI	ES				-
DATE	STEP	PR	OCEDURE CHAP	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			· ·						
				·					
				*					
D =t A1 =						·			
Part No		PAR #:							
	Reso	olution:						Date: _	<del></del>
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	l)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	on C	Chief Eng	QC Inspector
		•							
									185
		,							·
								·	



Dart Aerospace L
------------------

	•									
W/O:		WORK ORDER CHANGES								
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		· .								
		,	•	·						
				,						
				<del>:</del> ;					i	
Part No:		PAR #:	_ Fault Cate	gory:	NCR: Yes	NCR: Yes No DQA: Date:				
	R	esolution:	_ Dispositio	n:	QA: N/C C	A: N/C Closed:			Date:	
NCR:		W	ORK ORD	ER NON-CONFORM	ANCE (NCI	₹)		<u> </u>	, , , , , , , , , , , , , , , , , , , ,	
DATE	STEP	Description of NC	Corrective Action Section			Verification		Approval Appr	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	Section		Chief Eng	QC Inspector	
.: <u>.</u> :										
									£	
						be w. 1.				